

# How to update firmware on Windows?

- Sierra will provide OCT for Windows OS, please double click the exe file and wait until the process ends.

 99999999\_9907259\_SWI9X50C\_01.14.22.00\_00\_GENERIC\_002.057\_000.exe

- Notice, please do not remove or power off the module while flashing firmware.

```
CA\Users\vince\AppData\Local\Temp\FDT\fdt2.exe
FDT version: 1.0.1902.1
Awaiting adapter ...
Setting images preference ...
Resetting ...
Awaiting download port ...
Switching to streaming mode ...
Downloading images ...
Writing image 1
Flashing image 1
Awaiting adapter ...
Checking update status ...
Enabling selective suspend ...
Firmware image download succeeded.
Final Firmware update succeeded.

Preexisting images information:
Current:
  Firmware:
    ImageId: 002.035_003
    BuildId: 01.14.22.00_GENERIC
  Configuration:
    ImageId: 002.035_003
    BuildId: 01.14.22.00_GENERIC
Final images information:
Current:
  Firmware:
    ImageId: 002.057_000
    BuildId: 01.14.22.00_GENERIC
  Configuration:
    ImageId: 002.057_000
    BuildId: 01.14.22.00_GENERIC

OEM PRI: 9910009 001.003
IMEI: 353533104190791
Total time elapsed: 47110 ms.
Time to switch to boot mode: 23375 ms.
Images downloaded:
  Image ID: 002.057_000
  Build ID: 01.14.22.00_GENERIC
  write time: 250 ms
  additional flash time: 110 ms
Time to reset to application mode: 22594 ms.
Press Enter to continue ...
```